

EC2024-0674 ATTACHMENT 3

BYLAW NUMBER 25M2024

WHEREAS Council has considered report EC2024-0674 and deems it necessary to amend Bylaw 14M2012, the Wastewater Bylaw;

NOW, THEREFORE, THE COUNCIL OF THE CITY OF CALGARY ENACTS AS FOLLOWS:

- 1. Bylaw 14M2012, the Wastewater Bylaw as amended, is hereby further amended.
- 2. In section 3,
 - (a) in the definition of "CAN/CSA B481", the word "2007" is deleted and the following is substituted:

"2012"; and

- (b) in the definition of "owner", the following is added after subsection (iii) as subsection (iv):
 - "(iv) a business operating on the land or *premises*;".
- 3. In section 26:
 - (a) Subsection (4)(b) is deleted and the following is substituted:
 - "(b) keep a maintenance log for each *pre-treatment system* on the *premises*, in the form prescribed by the *Director, Water Services*, with a record of every inspection, servicing, and repair;
 - (b.1) keep maintenance logs in accordance with subsection (b) on the *premises* for a minimum of two years; and"; and
 - (b) The following is added after subsection 4(c) as section 26(4.1):
 - "(4.1) A *person* must not provide false or misleading information on a maintenance log under this *Bylaw*."
- 4. Section 27(1) is deleted in its entirety, and the following is substituted as sections 27(1), (1.1), and (1.2):
 - "27. (1) An *owner* of a business or a *premises* that is connected directly or indirectly to the *wastewater system*, and where food may be cooked,

processed, or prepared, and where a *fixture* or equipment releases *wastewater* that includes *Fats*, *Oil or Grease* must do the following:

- install a FOG interceptor at a location with adequate access on the upstream side of a monitoring access point in or on the premises to prevent FOG from passing into the wastewater system;
- (b) select and install a *FOG interceptor* which is properly sized and designed in accordance with the *CAN/CSA B481*;
- (c) ensure FOG interceptor meets the requirements of the National Plumbing Code of Canada;
- (d) ensure the *FOG interceptor* is installed in a location that has adequate access for cleaning;
- (e) ensure a minimum of 12in (300mm) clearance between the cover of the *FOG interceptor* and the bottom of the sink or other obstacle;
- (f) monitor, operate, and *properly maintain* a *FOG interceptor* at all times;
- (g) clean all FOG interceptors monthly or at an interval required by the Director, Water Services; and
- (h) dispose of exhaust hood wash water in a fixture that is connected to a FOG interceptor or haul such water to a location approved by the Director, Water Services.
- (1.1) For the purposes of subsection (1) above:
 - (a) "fixture" means a receptacle, sink, appliance, apparatus, or other device that releases or has the potential to release, wastewater or FOG and includes a floor drain:
 - (b) "adequate access" means easy access for proper cleaning and removal of FOG and sediments, allowing, at a minimum: access by a 50mm (2in) diameter vacuum hose, and for personnel to reach all removable internal components; and
 - (c) "properly maintain" means removing the entire contents and thoroughly cleaning the FOG interceptor.
- (1.2) The Director, Water Services may:
 - (a) prescribe the frequency of *FOG interceptor* cleanings; and
 - (b) prescribe approved locations for disposal of hauled hood wash water.".

- 5. In section 34(1)(c):
 - (a) the word "; and" in subsection (iv) is deleted and the following is substituted:

"."; and

- (b) subsection (v) is deleted in its entirety.
- 6. In section 34.1:
 - (a) subsection (2) is deleted and the following is substituted:
 - "(2) The operator of a *full service food vehicle* must dispose of *wastewater* at a location approved by the *Director, Water Services.*";
 - (b) subsection (3) is deleted; and
 - (c) after subsection (5), the following is added as section 34.1(6):
 - "(6) The operator of a *full-service food vehicle* must equip that vehicle with a greywater disposal connection as approved by the *Director, Water Services.*".
- 7. Sections 43(1), (2) and (3) are deleted and the following is substituted as sections 43(3.1) and 43(3.2):
 - "(3.1) Where:
 - (a) the Director, Community Planning;
 - (b) the *Director, Water Services*; or
 - (c) an Officer,

believes a *Person* has contravened any provision of this Bylaw, they may issue to the *Person* a *Remedial Order* to remedy the infraction.

- (3.2) A *Remedial Order* issued pursuant to this Bylaw may be served in accordance with the Community Standards Bylaw 32M2023.".
- 8. In Schedule "J" "Offences and Penalties":
 - (a) after:

Section	Description of Offences	Minimum Penalty	Specified Penalty
"26(4)(a)	Failing to obtain and retain manuals, instructions and specifications related to the installation, operation, maintenance and	\$100	\$200"

cleaning	of the pre-treatment system	
installed	at the <i>premises</i>	

the following is deleted under the headings indicated:

Section	Description of Offences	Minimum	Specified
		Penalty	Penalty
"26(4)(b)	Failing to maintain a maintenance schedule and record of each maintenance for the <i>pretreatment system</i> installed at a <i>premises</i> for a period of two years, including records for disposal of <i>waste residue</i>	\$100	\$500"

and the following is substituted in its place under the headings indicated:

Section	Description of Offences	Minimum Penalty	Specified Penalty
"26(4)(b)	Failure to keep a maintenance log in accordance with this Bylaw	\$100	\$500
26(4)(b.1)	Failure to keep maintenance logs for length of time required	\$100	\$500";

(b) after:

Section	Description of Offences	Minimum Penalty	Specified Penalty
"26(4)(c)	Failing to submit records requested by the	\$100	\$500"
	Director		

the following is deleted under the headings indicated:

Section	Description of Offences	Minimum Penalty	Specified Penalty
"27(1)(a)	Failing to install a <i>FOG interceptor</i> as required by subsection 27(1)(a)	\$500	\$2000
27(1)(b)	Failing to monitor, operate, properly maintain and clean each <i>FOG interceptor</i> as required by subsection 27(1)(b)	\$500	\$1500
27(1)(c)	Failing to ensure that wastewater does not exceed the maximum allowable concentration limits for FOG set out in Schedule C of the Bylaw	\$1000	\$3000
27(1)(d)	Failing to submit <i>interceptor</i> maintenance records requested by the <i>Director</i>	\$100	\$500"

and the following is substituted in its place under the headings indicated:

Section	Description of Offences	Minimum	Specified
		Penalty	Penalty

Page 4 of 6

"27(1)(a)	Failing to install a FOG interceptor at a location with adequate access	\$500	\$2000
27(1)(b)	Failing to select and install a properly designed FOG interceptor	\$500	\$2000
27(1)(c)	FOG interceptor fails to meet requirements of National Plumbing Code of Canada	\$500	\$2000
27(1)(d)	FOG interceptor installed in improper location	\$500	\$2000
27(1)(e)	FOG interceptor installed without appropriate clearance	\$500	\$2000
27(1)(f)	Failing to monitor, operate, and properly maintain a FOG interceptor	\$500	\$1500
27(1)(g)	Failing to clean FOG interceptor at required interval	\$500	\$1500
27(1)(h)	Failing to dispose of exhaust hood wash water in accordance with this <i>Bylaw</i>	\$500	\$1500";

and

(c) after the following:

Section	Description of Offences	Minimum Penalty	Specified Penalty
"34.1(5)	Failing to provide logbook upon request	\$100	\$200"

the following is added:

Section	Description of Offences	Minimum Penalty	Specified Penalty
"34.1(6)	Failing to equip Food Service Vehicle with a proper greywater disposal connection	\$500	\$1500".

SIGNED ON _____

9. This	Bylaw comes into force on the	day it is passed.	
READ A FI	RST TIME ON		
READ A SE	COND TIME ON		
READ A TH	IIRD TIME ON		
		MAYOR	
		SIGNED ON	
		CITY CLERK	