Community Association Response

JUNE 1, 2023 - INITIAL COMMENTS

[External] FW: LOC2017-0149-Circulation Package





i If there are problems with how this message is displayed, click here to view it in a web browser.

Click here to download pictures. To help protect your privacy, Outlook prevented automatic download of some pictures in this message.

This Message Is From an External Sender

This message came from outside your organization.

ATTENTION: Do not click links or open attachments from external senders unless you are certain it is safe to do so. Please forward suspicious/concerning email to spam@calqary.ca

Hi Felix, you requested comment from TPCA on this application. Just wondering why the LOC number is 2017 and not 2023?

Also a few comments which are more relevant to the DP stage but to give you a headsup:

- Is it possible to arrange combined black/blue/green carts for these 4plex developments. 12 carts can look very disorganized as we have seen at similar developments.
- We would like to see some type of protocol for exterior maintenance and appearance. Similar developments are often looking somewhat unkept and disorganized with no obligation of owners to arrange a condo board or combine efforts to cut grass or shovel snow, etc.

AUGUST 29, 2023 - ADDITIONAL COMMENTS

From: Arnie Brownlees

Sent: Tuesday, August 29, 2023 4:18 PM

To: Ochieng, Felix F.

Subject: [External] RE: LOC2017-0149-Circulation Package

This Message Is From an External Sender

This message came from outside your organization.

ATTENTION: Do not click links or open attachments from external senders unless you are certain it is safe to do so. Please forward suspicious/concerning email to spam@calqary.ca

Yes you can use my previous comments in addition to:

We want to see quality construction material such as brick/stone and acrylic stucco. Also concrete steps instead of wooden.